

Thermometer

Core Removal Tool Accessory




KEY FEATURES

- LCD read out
- Swivel Head
- On/off switch, hold test switch
- Spare battery
- Temperature range: -58°F (-50°C) to +302°F (150°C)

Description	Part No.	BAG QTY
Thermometer	CD3975	1

Braze-In Service Valves

Core Removal Tool Accessory



KEY FEATURES

Copper saddle valve for special use with CD3090 Tube Piercing Attachment and any core removal tool. Available to fit nine sizes of copper tubing. These ports are similar to the M Series fittings, but they are internally threaded to house a valve core, and come with a CD2245 cap.

Description	Part No.	BAG QTY
1/4"	CD3094	6
5/16"	CD3096	6
3/8"	CD3098	6
1/2"	CD3092	4
5/8"	CD3095	3
3/4"	CD3034	2
7/8"	CD3078	2
1-1/8"	CD3018	2